



PURCHASE ORDER

Procurement Unit
Telephone No.: 045-606-8142/606-8157

DELIVERY DUE DATE:

Maintenance of Airconditioning & Refrigeration (MARCO) Co., Inc.
Supplier : **Refrigeration (MARCO) Co., Inc.**
Address : 12 Matatag St. Brgy Piñahan, Quezon City
TIN#: 000-356-826-000 Vat Reg
Tel. No. : 922-3504/922-7365 Fax No.920-4598

PR No.: 2019-08-287
PO No.: 2019-746
Date: 11/20/2019
Mode of Procurement: Public Bidding

Please furnish this office the following articles subject to the terms and conditions contained herein:

Place of Delivery: Tarlac State University
Date of Delivery: _____

Delivery Term: 45 calendar days
Payment Term: N/30

Item No.	Unit	Description	Quantity	Unit Cost	Total Cost
1	pc	Air Conditioning Unit, Window Type Non-inverter, Capacity: 2.0 HP, Cooling capacity: 18,700Kj/h,Energy Efficiency Ratio 10.8Kj/h-W, Ampere Current 8.6, Power Input 1,850W, 220-230V, I Phase, 60Hz, Refrigerant R410A, with Remote Control,4-way Airflow Direction, Auto Horizontal Airflow (Two Motors), Exquisite Dust Filter, 24 Hours Timer, Auto Restart, Dry Function, Slide Chassis, Easy Claeen Filters Warranty: Five (5) years on compressor and one (1) year on parts and services	52	20,497.68	1,065,879.36

(Total Amount in Words) One Million Sixty-Five Thousand Eight Hundred Seventy Nine Pesos and 36/100 Only

Warranty shall be for a period minimum of three (3) months for expendable supplies, or a minimum period of one (1) year for non-expendable supplies. In case of failure to make full delivery within the time specified above, a penalty of one-tenth (1/10) of one percent for every day of delay shall be imposed.

Very truly yours,

DR. GENARD T. MARIAGA
VP, for Admin and Finance
Authorized Official

Conforme:

OLIVERT Y. DUYA

11/21/19 4:45pm

Maintenance of Airconditioning & Refrigeration (MARCO) Co., Inc.

(Signature over printed name & date)

Bank Account Name: Maintenance of Airconditioning & Refrigeration (MARCO) Co. Inc.

Bank Account Number: 0572-1023-78

Bank Name: Landbank of the Philippines

Bank Address: East Avenue Branch

Funds Available:

JESUS S. DANGANAN

Budget Officer IV

ALOBS No.:

Amount:

No.: TSU-PRO-SF-09

Revision No. 2

Effectivity Date : October 25, 2019

Page 1 of 1



PURCHASE ORDER

Procurement Unit
Telephone No.: 045-606-8142/606-8157

DELIVERY DUE DATE:

Supplier: **Maintenance of Airconditioning & Refrigeration (MARCO) Co., Inc.**
Address: 12 Matatag St. Brgy. Piñahan, Quezon City
TIN#: 000-356-826-000 Vat Reg
Tel. No.: 922-3504/922-7365 Fax No. 920-4598

PR No.: 2019-08-287
PO No.: 2019-752
Date: 11/20/2019

Mode of Procurement: **Public Bidding**

Please furnish this office the following articles subject to the terms and conditions contained herein:

Place of Delivery: Tarlac State University
Date of Delivery: _____

Delivery Term: 45 calendar days
Payment Term: N/30

Item No.	Unit	Description	Quantity	Unit Cost	Total Cost
2	pc	Air Conditioning Unit, Window Type Non-inverter, Capacity: 0.75 HP, Cooling capacity: 7,700Kj/h, Energy Efficiency Ratio 10.9Kj/h-W, Ampere Current 3.2, Power Input 750W, 220-230V, I Phase, 60Hz, Refrigerant R410A, with Remote Control, 4-way Airflow Direction, Auto Horizontal Airflow (Two Motors), Exquisite Dust Filter, 24 Hours Timer, Auto Restart, Dry Function, Slide Chassis, Easy Clean Filters Warranty: Five (5) years on compressor and one (1) year on parts and services	8	14,176.68	113,413.44
				Total	113,413.44

(Total Amount in Words) One Hundred Thirteen Thousand Four Hundred Thirteen Pesos & 44/100 Only

Warranty shall be for a period minimum of three (3) months for expendable supplies, or a minimum period of one (1) year for non-expendable supplies. In case of failure to make full delivery within the time specified above, a penalty of one-tenth (1/10) of one percent for every day of delay shall be imposed.

Very truly yours,

RECEIVED
06 DEC 2019

DR. GLENARD T. MADRIAGA
VP, for Admin and Finance
Authorized Official

Conforme: CLIVERT Y. DUYA 11/29/19 4:48 pm

Maintenance of Airconditioning & Refrigeration (MARCO) Co., Inc.

(Signature over printed name & date)

Bank Account Name: Maintenance of Airconditioning & Refrigeration (MARCO) Co., Inc.
Bank Account Number: 0572-1028-78
Bank Name: Landbank of the Philippines
Bank Address: East Avenue Branch

Funds Available:

JESUS S. DANGANAN
Budget Officer IV

ALOPS No. :
Amount :

No.: TSU-PRO-SF-09

Revision No. 2

Effectivity Date : October 25, 2019

Page 1 of 1